UNITED
TECHNOLOGIES
Pratt & Whitney

FACILITY Problembles - Main St. I.D. NO. CTD 990672081
FILE LOC. R-113
OTHER ROMS #2712

400 Main Street East Hartford, CT 06108 Environmental Compliance

December 5, 1989

U. S. Environmental Protection Agency JFK Federal Building Boston, MA 02203 ATTN: Ms. Julie Belaga

Connecticut Department of Environmental Protection 165 Capitol Avenue Hartford, CT 06106 ATTN: Ms. Leslie Carothers

Dear Ms. Belaga and Ms. Carothers:

This letter is intended to fulfill our obligation under 40 CFR 265.56(j) and 22a-449(C)(26)(f)(10) of the Code of Federal Regulations and the Regulations of the State of Connecticut, respectively, to report on any incident requiring the activation of our Contingency Plan.

Owner:

United Technologies Corporation One Financial Center Hartford, CT 06101 (203) 728-7000

Facility:

Pratt & Whitney 400 Main Street East Hartford, CT 06108 (203) 565-3833

Location: Waste Treatment Tanker Pad

Date of spill/incident: 12/5/89 Time: 0945 Hrs

Material involved: Nitric Acid - 50% Dilute

Quantity:Less than 10 gallons

Description or cause of spill/incident: A P & W truckdriver coupled up to tanker #153 while Nitric Acid was being pumped out. The acid spilled out the top hatch and from the disconnected hose.

Extent of contamination and injuries: Approximately one-half gallon of the solution reached the catch basin west of the truck pad. There were no injuries.

Corrective action taken: The acid that spilled on the ground was neutralized with sodium bicarbonate to ellimate any additional contamination of the storm sewer system.

The information on this report is correct to the best of my knowledge.

Richard E. Atwood

Supervisor

Environmental Compliance Group

REA/JJk/jjk